


DESIGN NO. GP/WA 120-02
ASSEMBLY RATING: 2 HOURS; NON-BEARING STAIRWALL

Shaft Side



Room Side